: VERTICAL REF DOOR INSTALLATION

Date: User: Wednesday, 2/21/2007 10:29:06 AM

Eric Charbonneau

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

: 30784

Estimate Number

: 12741

P.O. Number This Issue

:NIA

: 2/21/2007

Prsht Rev. : NC : NM First Issue

Previous Run

MIG:

Written By **Checked & Approved By**

Comment

: rev A 07.02.21 new issue EC

S.O. No. : ルル

: LARGE FAB ASSY

Project Number Drawing Revision Material

Part Number

Drawing Number

Drawing Name

Due Date

Description:

: EA2046925

D2046901 : N/A

: 1

: NIA : 2/28/2007

Qty:

2 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

ARM

1.0 EA2046929



Comment: Qtv.:

2.0

1.0000 Each(s)/Unit Total:

2.0000 Each(s)

ARM

EA2046928

batch: B30846

ARM GUIDE

8.0000 Each(s)

Comment: Qty.: 4.0000 Each(s)/Unit

ARM GUIDE

batch:

3.0 EA2046922

Total:

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

4.0000 Each(s)

LUG

LUG batch:

330785

EA2046926

DOOR PLATE



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

2.0000 Each(s)

DOOR PLATE

batch: 1630787

DOOR PLATE

5.0

4.0

EA2046927

1.0000 Each(s)/Unit Total:

2.0000 Each(s)

DOOR PLATE

Comment: Qty.:

batch: \$80786

	lednesday, 2/21/2007 10:29:06 AM ric Charbonneau	Process Sheet
Custome	er: CU-DAR001 Dart Helicopters Servi	
	00704	D. 4 44 L [A2046025
Job Number:	er: 30/84	Part Number: EA2046925
OD RUIDG.		
Seq. #:	Machine Or Operation:	Description :
6.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
Comment: LARGE FABRICATION RESOURCE 1		
	1- Weld assembly as per dwg	Maz/22 (3)
	4130 welding rod batch: MG	INSPECT WORK TO CURRENT STEP
7.0	QC5	INSPECT WORK TO CORRENT STEP
Com	ment: INSPECT WORK TO CURRE	
8.0	cca	VISUAL WELDING INSPECTION
	ment: VISUAL WELDING INSPECTI	
9.0	PACKAGING 1	PACKAGING RESOURCE #1
Comment: PACKAGING RESOURCE #1		
	Identify and Stock Location:	(207/02/23 @
Job Completion		CZ07/02/23
8-1	Degrease,	prime per dug 5204690; ml072223
8.7	QC3	E 07,02.23

